NTSB ID: SEA02LA047 Aircraft Registration Number: N5413J

Occurrence Date: 03/03/2002 Most Critical Injury: None

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Longmont	со	80503	1100	MST	
Airport Proximity: On Airport	Distance From	m Landing Facility:		Direction Fro	m Airport:

Aircraft Information Summary

Aircraft Manufacturer	Model/Series	Type of Aircraft
Cessna	172N	Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On March 3, 2002, at 1100 mountain standard time, a Cessna 172N, N5413J, sustained substantial damage when it went off the side of runway 29 and flipped over during landing at Vance Brand Airport (2V2) in Longmont, Colorado. The student pilot, the solo occupant, was not injured. The aircraft was registered to a private owner and was being operated by Flatirons Aviation of Boulder, Colorado, on a visual flight rules (VFR) instructional flight under the provisions of Title 14 CFR Part 91. Visual meteorological conditions prevailed, and no flight plan was filed for the flight. The flight departed Boulder Municipal Airport (1V5), Boulder, Colorado, about 1040.

The student reported that the runway was icy at the time of the landing. He reported that he attempted a soft field landing at 60 knots. He stated that he slowed to 30 knots, at which point the aircraft hit a patch of ice. He reported that the airplane skidded to the left, the nosewheel hit a large mound of snow, and the airplane flipped onto its back. The student pilot reported that no mechanical failure or malfunction was involved in the accident. The student pilot reported in his narrative of the accident that he had a 10-knot tailwind, but reported in the weather data blocks on his NTSB pilot accident report that winds were from 290 degrees at 10 knots (he also filled in 10 knots in the "Gusts" weather data block.) The student reported a temperature of 40 degrees F at the time of the accident on his NTSB accident report. At 1045, Jeffco Airport in Broomfield, Colorado, reported a temperature of -4 degrees C (25 degrees F) and variable winds at 3 knots.

According to the U.S. Government Airport/Facility Directory (A/FD), Vance Brand Airport runway 29 is a 4,800-foot by 75-foot concrete runway.

NTSB ID: SEA02LA047

Occurrence Date: 03/03/2002

AVIATION Occurre				e: Accident							
Landing Facility/Approach In	formation										
Airport Name		А	Airport ID:	Airport Eleva	ution	Run	Runway Used Runwa			th F	Runway Width
Vance Brand		2	2V2	5052 Ft.	. MSL	. 29		4800			75
Runway Surface Type: Concrete											
Runway Surface Condition: Ice					_						
Type Instrument Approach: NONE	Ē										
VFR Approach/Landing: Full Stop)										
Aircraft Information											
Aircraft Manufacturer Cessna			Model 172N	I/Series N					Serial 1727	Number 3784	
Airworthiness Certificate(s): Normal; Utility											
Landing Gear Type: Tricycle											
Homebuilt Aircraft? No	Number of Seats: 4	4	Certifie	ed Max Gross W	√t.		LBS Numbe		er of Engi	ines: 1	
Engine Type: Reciprocating				Engine Manufacturer: Model/Series: Uycoming O-320						F	Rated Power:
- Aircraft Inspection Information											
Type of Last Inspection		[Date of Last Inspection Time S			Time Si	Since Last Inspection			Airframe	e Total Time
Unknown								Ho	ours		Hours
- Emergency Locator Transmitter (ELT) Information										
ELT Installed? Yes	ELT Operate	ed? Yes			ELT	Aided in	in Locating A	ccident S	site? No)	
Owner/Operator Information											
Registered Aircraft Owner			Street Address 2810 Olson Dr								
Carl E. Lawrence			City							State	
			Boulder CO 80303: Street Address								803031008
Operator of Aircraft			Sileei	Address 3300 Air	port F	Rd. Box	: L				
Flatirons Aviation			City							State	Zip Code
									co	80301	
Operator Does Business As:						0	perator Desig	jnator Co	ode: YF	AA	
- Type of U.S. Certificate(s) Held: Air Carrier Operating Certificate(s):	On-demand Air [↑]	 Гахі									
All Garrier Operating Continuations,											
Operating Certificate:	Operating Certificate: Operator Certificate:										
Regulation Flight Conducted Under	r: Part 91: Genera	al Aviatic	on								
Type of Flight Operation Conducted	d: Instructional										
]	FACTU	AL REPC	ORT - AVIATI	ION						Page 2

NTSB ID: SEA02LA047

Occurrence Date: 03/03/2002

AVIATI	AVIATION Occurrence Type: Accident												
First Pilot Information													
Name					City					State	D	ate of Birth	Age
On File					On File	n File On File					ile	On File	37
Sex: M Seat Occupied	x: M Seat Occupied: Left Principal Profession: Unknown Certificate Number: On File												
Certificate(s): Stud	lent												
Airplane Rating(s): None													
Rotorcraft/Glider/LTA: None													
Instrument Rating(s): None	е												
Instructor Rating(s): None													
Type Rating/Endorsement for	or Accident/In	ncident Aircra	ft? Yes			С	urrent B	iennial F	ight Re	eview?			
Medical Cert.: Class 3	Medica	al Cert. Status	s: Valid Med	dicalno wa	aivers/li	m.		Date	e of Las	st Med	ical Ex	am: 12/2001	
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nigh	ıt	Actual	Instrument Re			torcraft	Glider	Lighter Than Air
Total Time	38	34	38			3							
Pilot In Command(PIC)	10	10	10			3		_		+			
Instructor	00	0.4								+			
Last 90 Days Last 30 Days	38	34 8	38 8			3				+			
Last 24 Hours	1	1	1			\neg				+			
Seatbelt Used? Yes	Shou	ılder Harness	Used? Yes		-	Toxico	ology Pe	rformed?	No		Sec	cond Pilot? No)
					I_								
Flight Plan/Itinerary													
Type of Flight Plan Filed: No	one												
Departure Point						State Airport Iden		entifier	fier Departur		ure Time	Time Zone	
Boulder						СО		1V5		1040			MST
Destination						State		Airport Id	entifier				
Same as Accident/Incident Location								2V2					
Type of Clearance: None					·								
Type of Airspace: Class G													
Weather Information													
Source of Briefing: Unknown													
Method of Briefing: Teleph	none												
			FACTUAL	REPORT	- AVIA	OIT.	١						Page 3

NTSB ID: SEA02LA047

Occurrence Date: 03/03/2002

Occurrence Type: Accident

	Occurrence Type: Accident										
Weather	Information										
WOF ID	Observation Time	Time Zone	WOF Eleva	tion	WOF D	WOF Distance From Accident Site Direction					cident Site
			F	t. MSL				NM			Deg. Mag.
Sky/Lowes	r St Cloud Condition: Clea	r				Ft. AG	SL	Condition o	of Ligh	nt: Day	0 0
Lowest Ce	illing: None		Fi	. AGL	Visib	ility:	40	SM	Altimeter: "		
Temperatu		Dew Point:	°C	Wind	Direction:	290			Dei	nsity Altitude:	Ft.
Wind Spee		Gusts:		+			dent S	ite: Visual C			
Visibility (F	RVR): Ft.	Visibility (RVV)	SM		y of Precipit					
Restriction	s to Visibility: None										
Type of Pr	ecipitation: None										
Accident	Information										
Aircraft Da	mage: Substantial		Aircraft Fi	re: None)			Aircraft Exp	losio	n None	
Classificati	ion: U.S. Registered/U	.S. Soil									
- Injury Su	mmary Matrix	Fatal	Serious Mir	or	None	TOTAL					
First Pi	ilot				1	1					
Second	d Pilot										
Studer	nt Pilot										
Flight I	nstructor						1				
Check	Pilot						1				
Flight E	Engineer]				
Cabin /	Attendants]				
Other (Crew]				
Passer	ngers						1				
- TOTAL /	ABOARD -				1	1	1				
Other (Ground						1				
- GRANI	TOTAL -				1	1	1				

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB	10	0	A 001	A A 4 =
NIISE	11).	\sim	41171	411/1/

Occurrence Date: 03/03/2002

Occurrence Type: Accident

Δ	dm	inis	trativ	r⊵ Int	f∩rm	ation
$\overline{}$	ulli	บบอ	uauv			alioi

Investigator-In-Charge (IIC)

Gregg Nesemeier

Additional Persons Participating in This Accident/Incident Investigation:

Tom Forchtner Aviation Safety Inspector FAA - Denver FSDO 26805 East 68th Avenue, Suite 200 Denver, CO 80249